

CO₂ Sensors

Fast Response Range—SprintIR^{6S}



- Low power / energy consumption—35mW
- Measures up to 100% CO₂ concentration
- Ultra-fast response rate; 6X faster than the SprintIRa
- High speed sensing; 20 measurements per second (20Hz)
- Sample volume of only 2ml
- Solid-state; no moving parts, no heated filaments
- Digital (UART) output







Power Consumption

















BENEFITS

- Very fast response (see graph page 2)
- Ideal for very low power and battery applications
- Suitable for wireless, portable, wearable and self-powered
- Fits neatly inside compact instruments

CO₂ MEASUREMENT SPECIFICATIONS

Non-dispersive infrared (NDIR) Sensing method

absorption

Sample method Flow through adaptor

0-5%, 0-20%, 0-100% Measurement range Accuracy^c ±70ppm / ±5% of reading

(100% range ±300ppm

±5% of reading)

Measurement noise <10% of reading (no digital filtering)

Pressure dependence^d 0.15% of reading per mbar in normal atmospheric conditions

Operating pressure range^e 500mbar to 2 bar with flow through

adaptor

Response time (a step Flow rate dependant; refer to graph to change in gas level)f overleaf

Update rate

20Hz

TECHNICAL SPECIFICATIONS

Supply voltage $3.25 - 5.5 V_{DC}$

(3.3V recommended)

<15mA (average)

100mA Peak

Power consumption^b 35mW

Output type 3.3V TTL level UART

Temperature

Current

0°C to +50°C (standard) Operating:

-25°C to +55°C (extended)

-30°C to +70°C Storage:

Humidity 0-95% Rh, non-condensing

Start-up time < 30 seconds




- Based on 0.1 litres per minute flow rate and 0-10% step change in CO₂ concentration.
- Power measurements for standard CO₂ sensor with 20 readings per second
- All measurements are at NTP unless otherwise stated.
- Calibrated for 1013mbar. External pressure calibration required.
- ISweek can supply advanced pressure correction advice when operating outside normal atmospheric conditions.
- Response time to a step change in gas level is dependent on application/filter/flow rate/diffusion.

ISweek www.isweek.com




NOTE: T90 time measured from 0 to 10% CO₂. Digital filter switched off.



OUTLINE DRAWING & ELECTRICAL CONNECTIONS

2x5 0.1" header. PIN 1 is identified on the dimensional drawing. All dimensions shown in mm.



RX-IN

Pin 1 is identified on the dimensional	al drawing.
Pin 2 should not be connected.	

Pins 4 and 6 do not require connection and are internally connected to GND.

The zeroing options are for hardware zeroing (both active low).

0.5

5.5

These functions can also be implemented by sending a serial command (recommended).

Typical connections for digital interface are GND, 3.3V, Rx and Tx. Note that the Vh for the serial Tx line will be 3V regardless of the supply voltage.

V+

TX-OUT

RX-IN

3.3V to 5V

UART Tx from sensor


V_{oh} = 3V UART Rx to sensor

used for configuration





Generate your specific part number using the convention shown below. Use only the numbers that correspond to the sensor option you require — omit those you do not.



* NOTE: Temperature & humidity option not available on voltage output variant.

EXAMPLES:

• SprintIR6S -5 = Standard temperature range, 5% range.



Do not exceed maximum ratings and ensure sensor(s) are operated in accordance with their requirements.

Carefully follow all wiring instructions. Incorrect wiring can cause permanent damage to the device.

Do NOT use chemical cleaning agents.

Failure to comply with these instructions may result in product damage.



INFORMATION

As customer applications are outside of Week Technology Ltd.'s control, the information provided is given without legal responsibility. Customers should test under their own conditions to ensure that the equipment is suitable for their intended application.

General Note: Week Technology Ltd. reserves the right to make changes to product specifications without notice or liability. All information is subject to Week Technology Ltd.'s own data and considered accurate at time of going to print.

DS-0149 REV 2

© 2018

ISweek www.isweek.com

Add: 16/F, Bldg. #3, Zhongke Mansion, No.1 Hi-Tech S. Rd, Hi-Tech Park South, Shenzhen, Guangdong, 518067 P.R.China

Tel: +86-755-83289069

Fax: +86-755-83289052

E-mail: sales@isweek.com